



Dakota Collectibles

World's Largest Supplier of Stock Embroidery Designs

Adding Sparkle to your Embroidery

Items you will need:

Stones/crystals heat setting tool with a variety of tips

Heat set stones/crystals that compliment the item you are decorating

Tweezers

A piece of cardboard

Always test the fabric to make sure it can handle the heat.

Follow the directions that are included with your heat setting tool.

1. Embroider your design.
2. Lay a piece of cardboard between the fabric on a hard surface.
3. Lay out the stones/crystals with the tweezers.
4. Heat your setting tool.
5. Adhere your stones/crystals.